



State Water Resources Control Board

Division of Drinking Water

September 6, 2016 Certified Mail/Return 7012 3460 0003 1112 7550

Mendocino National Forest – Letts Lake 825 North Humboldt Avenue Willows, CA 95988

Attention: Randy Jero, Recreation Work Lead

RE: Mendocino National Forest – Letts Lake, Public Water System No. 0600056 –

Citation No. 21-16C-023 for Exceedance of the Bacteriological Maximum

Contaminant Level in August of 2016.

Enclosed is a citation issued to Mendocino National Forest – Letts Lake (Water System). The citation is being issued because the Water System failed to achieve the drinking water standard for total coliform bacteria during August of 2016. Please read this citation carefully and complete all directives. Public notification is required to inform consumers that the standard was not achieved during this time period.

Because your water system had two or more total coliform-positive samples in a month, the Federal Revised Total Coliform Rule requires your water system to conduct a Level 1 Assessment. We are advising you to comply with the new rule and conduct the assessment as specified in the directives of this citation.

Note that Section 116577 of the California Safe Drinking Water Act provides for the Division to be reimbursed by the Water System for costs incurred for preparing and issuing a citation. In accordance with Section 116577, the Water System will be billed for the preparation and issuance of this citation.

If you have any questions regarding this matter, please call Paul Rowe at (530) 224-4866 or me at (530) 224-4861.

Sincerely,

Reese B. Crenshaw, P.E. Valley District Engineer

Drinking Water Field Operations Branch

Enclosure

FELICIA MARCUS, CHAIR | THOMAS HOWARD, EXECUTIVE DIRECTOR

Citation No	. 21-16C-023	
		STATE OF CALIFORNIA
	WAT	ER RESOURCES CONTROL BOARD
	!	DIVISION OF DRINKING WATER
Public Wate	er System:	Mendocino National Forest - Letts Lake
Water Syste	em No.:	0600056
T	Mandadina	Netional Farest Lotte Loke
10:		National Forest - Letts Lake
		/ Jero, Recreation Work Lead
	vviiiows, CA	90900
'		
Issued:	September 6	3, 2016
	VIA CERTIF	TED MAIL
	7012 3460 0	0003 1112 7550
		•
·	C	ITATION FOR NONCOMPLIANCE
	With T	itle 22 California Code of Regulations
		Section 64426.1(b)
Section 1166	350 of the Cal	lifornia Health and Safety Code (CHSC) authorizes the
issuance of a	a citation for f	ailure to comply with a requirement of the California Safe
Drinking Wa	ter Act (CHSC	C, Division 104, Part 12, Chapter 4, commencing with
Section 1162	270), or any re	egulation, standard, permit, or order issued thereunder.
	Public Water Water Syste To: Issued: Section 1166 issuance of a Drinking Wa	Public Water System: Water System No.: To: Mendocino I Attn: Randy 825 North H Willows, CA Issued: September 6 VIA CERTIF 7012 3460 C With T Section 116650 of the Cal issuance of a citation for for I Drinking Water Act (CHSC)

The State Water Resources Control Board (hereinafter "State Board"), acting by and through its Division of Drinking Water (hereinafter "Division") and the Deputy Director for the Division, hereby issues a citation to Mendocino National Forest - Letts Lake for failure to comply with Section 64426.1(b), Title 22, of the California Code of Regulations (CCR).

APPLICABLE AUTHORITIES

Section 116650 of the CHSC states:

(a) If the Department determines that a public water system is in violation of this chapter or any regulation, permit, standard, citation, or order issued or adopted thereunder, the department may issue a citation to the public water system. The citation shall be served upon the public water system personally or by certified mail. Service shall be deemed effective as of the date of personal service or the date of receipt of the certified mail. If a person to whom a citation is directed refuses to accept delivery of the certified mail, the date of service shall be deemed to be the date of mailing.

(b) Each citation shall be in writing and shall describe the nature of the violation or violations, including a reference to the statutory provision, standard, order, citation, permit, or regulation alleged to have been violated.

(c) A citation may specify a date for elimination or correction of the condition constituting the violation.

1	(d) A citation may include the assessment of a penalty as specified in
2	subdivision (e).
3	
4	(e) The department may assess a penalty in an amount not to exceed
5	one thousand dollars (\$1,000) per day for each day that a violation
6	occurred, and for each day that a violation continues to occur. A
7	separate penalty may be assessed for each violation.
8	
9	Section 64426.1(b), Title 22, of the CCR states:
10	
11	(b) A public water system is in violation of the total coliform
12	maximum contaminant level (MCL) when any of the following
13	occurs:
14	
15	(1) For a public water system which collects at least 40
16	samples per month, more than 5.0 percent of the
17	samples collected during any month are total coliform-
18	positive; or
19	
20	(2) For a public water system which collects fewer than
21	40 samples per month, more than one sample
22	collected during any month is total coliform-positive; or
23	
24	(3) Any repeat sample is fecal coliform-positive or E. coli-
25	positive; or
26	·

1 2

(4) Any repeat sample following a fecal coliform-positive or E. coli-positive routine sample is total coliform-positive.

. 15

STATEMENT OF FACTS

The Mendocino National Forest - Letts Lake, domestic water system (Water System) is classified as a transient noncommunity water system serving approximately 100 persons per day. In accordance with Section 64423 of Title 22, the Water System is required to collect one routine bacteriological sample per month, unless there was a positive bacteriological sample the previous month, in which case, five routine bacteriological samples are required. On August 18, 2016, the Water System collected one routine sample from the distribution system, which contained total coliform bacteria. Four repeat samples were collected on August 23, 2016. All four repeat samples showed the presence of total coliform bacteria. The cause of the contamination was unknown. No sample discussed herein was positive for E. coli.

DETERMINATIONS

The Division has determined that the Water System violated Section 64426.1(b)(2), Title 22, of the CCR, in that the Water System exceeded the total coliform MCL during the month of August 2016.

DIRECTIVES

The Water System is hereby directed to take the following actions:

1. Comply with Section 64426.1, Title 22, of the CCR in all future monitoring periods.

- 2. Within 30 days of the issuance of this Citation, provide public notification in accordance with Attachment 'A', to all persons served by the Water System of the MCL violation as required by Section 64463.4 and Section 64465, Title 22, of the CCR. Notification shall be completed in accordance with the following:
 - (A) Provide the notice by posting in conspicuous locations throughout the area served by the water system.
- 3. Changes and/or modifications to Attachment A shall be not be made unless approved by the Division.
- 4. Complete and return **Attachment 'B'** "Certification of Completion of Public Notification" form **within 10 days** of giving public notice. A copy of the notice used to provide public notification shall be attached to the form.
- 5. Within 30 days of the issuance of this Citation, pursuant to the Federal Revised Total Coliform Rule, conduct a level 1 assessment of the Water System (use attached form) and return to the address identified below by October 6, 2016.
- 6. Collect and report five (5) routine bacteriological samples in the distribution system in the month of **September 2016**.
- The completed and signed copy of Attachment 'B' shall be submitted to the following address:

Reese B. Crenshaw, P. E.

Valley District Engineer

Drinking Water Field Operations

Division of Drinking Water

State Water Resources Control Board

364 Knollcrest Drive, Suite 101

Redding, CA 96002

(530) 224-4800

Nothing in this Citation relieves the Water System of its obligation to meet the requirements of Health and Safety Code, Division 104, Part 12, Chapter 4 (California Safe Drinking Water Act), or any regulation, permit, standard or order issued or adopted thereunder.

The Division reserves the right to make such modifications to this Citation, as it may deem necessary to protect public health and safety. Such modifications may be issued as amendments to this Citation and shall be effective upon issuance.

FURTHER ENFORCEMENT ACTION

The California SDWA authorizes the State Board to: issue citation with assessment of administrative penalties to a public water system for violation or continued violation of the requirements of the California SDWA or any permit, regulation, permit or order issued or adopted thereunder including, but not limited to, failure to correct a violation identified in a citation or compliance order. The California SDWA also authorizes the State Board to take action to suspend or revoke a permit that has been issued to a public water system if the system has violated applicable law or regulations or has failed to comply with an order of the State Board; and to petition the superior court to take various enforcement measures against a public water system that has failed to comply with violates an order of the State Board. The

1 .	State Board does not waive any further enforcement action by issuance of this
2	citation.
3	
4	PARTIES BOUND
5	This Citation shall apply to and be binding upon the Water System, its officers,
6	directors, agents, employees, contractors, successors, and assignees.
7	n en
8	SEVERABILITY
9	The directives of this Citation are severable, and the Water System shall comply with
10	each and every provision thereof notwithstanding the effectiveness of any other
11	provision.
12	
13	
14	
15	R. Crenslan 9/6/16
16	Reese B. Crenshaw, P.E., District Engineer Date
17	Valley District
18	Drinking Water Field Operations Branch
19	
20	Attachments:
21	'A' Public Notification Template
22	'B' Certification of Completion
23 24	Level 1 Assessment Form

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

Este informe contiene información muy importante sobre su agua potable.

Tradúzcalo o hable con alguien que lo entienda bien.

The Mendocino National Forest - Letts Lake water system did not meet Bacteriological Drinking Water Standards in August of 2016

Our water system violated the bacteriological drinking water standard for August of 2016. As our customers, you have a right to know what you should do, what happened, and what we are doing to correct this situation.

We routinely monitor for the presence of drinking water contaminants. We took five (5) samples to test for the presence of coliform bacteria during August of 2016. All five samples showed the presence of total coliform. The standard is that no more than one (1) sample per month may have total coliform.

What should I do?

- You do not need to boil your water or take other corrective actions. This is not an emergency; if it had been, you would have been notified immediately.
- Usually, coliforms are a sign that there could be a problem with the treatment or
 distribution system (pipes). Whenever we test for total coliform bacteria in any sample,
 we also test to see if other bacteria of greater concern, such as fecal coliform or *E. coli*,
 are present. We did not find E. Coli bacteria in our testing.
- People with severely compromised immune systems, infants, and some elderly may be at increased risk. These people should seek advice about drinking water from their health care providers. General guidelines on ways to lessen the risk of infection by microbes are available from U.S. EPA's Safe Drinking Water Hotline at 1(800) 426-4791.
- If you have other health issues concerning the consumption of this water, you may wish to consult your doctor.

What happened? What is being done?

In August of 2016, Five out of five water samples tested positive for total coliform organisms. We will be disinfecting the water system during the week of September 5, 2016 and will recollect water samples for analysis on, 2016.
For more information, please contact Randy Jero @ 530-934-1269
State Water System ID#: 0600056

CERTIFICATION OF COMPLETION OF PUBLIC NOTIFICATION

This form, when completed and returned to the Division of Drinking Water (364 Knollcrest Drive, Suite 101, Redding, CA 96002 or fax to 530-224-4844), serves as certification that public notification to water users was completed as required by the California Water Quality and Monitoring Regulations. Completing public notification and providing the Division with certification is important. Failure to do so will result in additional hourly time charges to your water utility and may result in a formal enforcement action with monetary penalties.

Public water System Name <u>Wiendocino National Forest</u>
Public Water System No. 0600056
Public notification for the August 2016 bacteriological failure was performed by the following method:
Posting in conspicuous locations throughout the area served by the water system. Please indicate the locations and date(s) the notice was posted:
I hereby certify that the above information is factual.
Printed Name
Signature
Date

STATE OF CALIFORNIA WATER RESOURCES CONTROL BOARD DIVISION OF DRINKING WATER



RTCR Level 1 Assessment Report Form for Positive Total Coliform Investigation

See the RTCR Level 1 Assessment Guidance and Tips document for additional infomation.

This assessment is intended to review general water system infrastructure, system operation and sampling protocols for potential sources of contamination. This To avoid a violation, an assessment report must be completed and returned to your local regulatory agency no later than 30 days after the trigger date. form should be completed by a knowledgeable representative of the water system.

SYST	SYSTEM NAME: Click here to enter text.	Trigger Da	Trigger Date: Click here to enter a date.	nter a date.
SYST	SYSTEM #: Click here to enter text.	Investigati	ion Date:Click her	Investigation Date: Click here to enter a date.
#	Senss)	Yes/No	N/A Potentially	If Yes or Potentially, Identify
н	Unusual occurrences with the water system since			
	the last negative routine bacteriological sample:			
	Loss of pressure <5 psi	□N □A		
	Heavy precipitation and/or flooding	□N □A		
	Customer complaints of water quality or pressure	□N □A		
	Evidence of unauthorized access/vandalism	N □V		:
	Interruption in disinfection treatment	□N □A		
7	Changes to water system since last negative			
	Piping modified or repaired	N C		
	System components replaced or repaired	N DY		
	Changes in operational procedures or personnel	□N □A		
m	Groundwater source contamination:			Proceed to section 4 if groundwater is not used.
	Repeat bacteriological sample(s) from raw source	N □Y		
	Water is positive for total colliding Wells:			
	Cracks or holes in the well casing above grade	□N □A		
	Water can leak through well top seal	□N □A		
	The well is not equipped with a downturned	□N □A		
	screened vent.			
	Water can leak through well head penetrations for	□ N □ A		
	electrical or sounding equipment			
	Leaking pipes or standing water around the well(s)	N □ V		
	Springs and/or Horizontal Wells:			

RTCR Level 1. Assessment Report Form for Positive Total Coliform Investigation

Page 2 of 3

		The collection site is overgrown with vegetation	□N □		
Surface of animal activity around the collection site (grazing/burrowing) Rodents, insects or roots in the spring box Surface water or GWUDI treatment issues CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CT not met at all times CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water can enter CD penings in tank roof that rain water systems CD penings in roof that rain roof timtusion, for underground tanks CD penings in roof that can roof that can roof intrusion, for underground tanks CD penings in roof that roof that can roof intrusion, for underground tanks CD penings in roof that can roof that can roof intrusion for underground tanks CD penings in roof that roof that can roof intrusion for underground tanks CD penings in the previous calendar year. CD penings are wet, leaking or dirty CD penings are wet, leaking or dirty CD penings are wet, leaking or dirty CD penings when reviewing historical monitoring? CD penings when reviewing historical monitoring? CD penings of there a seasonal patter in positive samples CD penings of the roof control in the roof in th		Flowing/standing water around the collection site	1		
Surface water or GWUDI treatment issues CT not met at all times Spikes in raw or filtered water turbidity Alarms and auto shutdowns are not properly set or Y□N□ Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Topenings in tank roof that rain water can enter Openings in tank roof that rain water can enter Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals N□N□ Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample iste are not the ones identified in the sporved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Evidence of animal activity around the collection site (grazing/hurrowing)	i		
Surface water or GWUDI treatment issues CT not met at all times CT not met at all times CT not met at all times Spikes in raw or filtered water turbidity Alarms and auto shutdowns are not properly set or Innitioning. Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Rodents, birds, insects or other unexpected Matchial inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals burrowing or nesting into the tank roof intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valwed off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample taps are wet, leaking or dirty The sample collector was not properly trained Ich when reviewing historical monitoring? Other		Rodents, insects or roots in the spring box			
CT not met at all times Spikes in raw or filtered water turbidity Alarms and auto shutdowns are not properly set or functioning. Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Nodenits, birds, insects or other unexpected Tank air vents are not properly screened to Trank air vents are not properly screened to Prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals Toot intrusion, for underground tanks Toot intrusion system Toot intrusion, for underground tanks Toot intrusion Toot intrus	4	Surface water or GWUDI treatment issues			
Spikes in raw or filtered water turbidity Alarms and auto shutdowns are not properly set or functioning. Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Rodents, birds, insects or other unexpected materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals Low pressure transmission lines Distribution system Low pressure transmission lines Dead end lines Any certified backflow prevention devices not the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the previous calendar year. Sample collector was not properly trained The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		CT not met at all times			
Alarms and auto shutdowns are not properly set or functioning. Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Openings in tank roof that rain water can enter Rodents, birds, insects or other unexpected materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals I cover intrusion, for underground tanks I cove intrusion, for underground tanks Low pressure transmission lines Low pressure transmission lines I cover intrusion, for underground tanks Low pressure transmission lines I cover intrusion system Low pressure transmission lines N □ N □ □ Low pressure transmission lines N □ N □ □ Low pressure transmission lines N □ N □ □ Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained N □ N □ □ Sample taps are wet, leaking or dirty The sample collector was not properly trained N □ N □ □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty N □ N □ Sample taps are wet, leaking or dirty		Spikes in raw or filtered water turbidity			
functioning. Tank(s) storage, clearwell, backwash return: Openings in tank roof that rain water can enter Rodents, birds, insects or other unexpected materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked root intrusion, for underground tanks root intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained shen reviewing historical monitoring? Other		auto shutdowns are not properly s	ı		
Tank(s) storage, clearwell, backwash return: □ Depnings in tank roof that rain water can enter □ □		functioning.			
Nodents, birds, insects or other unexpected Rodents, birds, insects or other unexpected Materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals Hurrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Distribution system Low pressure transmission lines N□ N□ Dead end lines Interties with non-potable water systems or Sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples When reviewing historical monitoring? Other	2	Tank(s) storage, clearwell, backwash return:			Proceed to section 6 if there are no tanks.
Rodents, birds, insects or other unexpected materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines N□ □ Any certified backflow prevention devices not transmission director was not the ones identified in the approved bacteriological sample siting plan. Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Inhere a seasonal pattern in positive samples N□ □ N		Openings in tank roof that rain water can enter			
materials inside tank Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals For redwood tanks, signs of birds/animals Troot intrusion, for underground tanks Toot intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or Sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample collector was not properly trained I he sample collector was not properly trained I he sample collector was not properly trained Is there a seasonal pattern in positive samples When reviewing historical monitoring? Other		Rodents, birds, insects or other unexpected			
Tank air vents are not properly screened to prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or y□ N□ Sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		materials inside tank			
prevent insects from entering. Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Tank air vents are not properly screened to			
Hatches or access ladders left unlocked For redwood tanks, signs of birds/animals burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample site and sampling procedures Sample site and sampling procedures Sample collector was not properly trained The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		prevent insects from entering.			
For redwood tanks, signs of birds/animals burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Low pressure transmission lines Dead end lines Interties with non-potable water systems or Y□ N□ Sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Hatches or access ladders left unlocked			
burrowing or nesting into the tank root intrusion, for underground tanks Distribution system Low pressure transmission lines Low pressure transmission lines Dead end lines Interties with non-potable water systems or Y□ N□ sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		For redwood tanks, signs of birds/animals			
root intrusion, for underground tanks Distribution system Low pressure transmission lines Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		burrowing or nesting into the tank			
Distribution system Low pressure transmission lines Y□ N□ Dead end lines Y□ N□ Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Y□ N□ □ Sample sites are not the ones identified in the approved bacteriological sample siting plan. Y□ N□ □ Sample taps are wet, leaking or dirty Y□ N□ □ The sample collector was not properly trained Y□ N□ □ Is there a seasonal pattern in positive samples Y□ N□ □ when reviewing historical monitoring? Y□ N□ □		root intrusion, for underground tanks	- 1		
Low pressure transmission lines Dead end lines Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other	9	Distribution system			
Dead end lines Y□ N□ N□		Low pressure transmission lines	N □ V		
Interties with non-potable water systems or sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Dead end lines			
sources (even if valved off) Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Interties with non-potable water systems or			
Any certified backflow prevention devices not tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		sources (even if valved off)	- 1		
tested in the previous calendar year. Sample site and sampling procedures Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Any certified backflow prevention devices not		,	•
Sample site and sampling procedures Y□ N□ Sample sites are not the ones identified in the approved bacteriological sample siting plan. Y□ N□ Sample taps are wet, leaking or dirty Y□ N□ The sample collector was not properly trained Y□ N□ Is there a seasonal pattern in positive samples Y□ N□ when reviewing historical monitoring? Y□ N□		tested in the previous calendar year.			
Sample sites are not the ones identified in the approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other	7	Sample site and sampling procedures			
approved bacteriological sample siting plan. Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		Sample sites are not the ones identified in the			
Sample taps are wet, leaking or dirty The sample collector was not properly trained Is there a seasonal pattern in positive samples when reviewing historical monitoring? Other		approved bacteriological sample siting plan.			
The sample collector was not properly trained Y□N□ Is there a seasonal pattern in positive samples Y□N□ when reviewing historical monitoring? Other		Sample taps are wet, leaking or dirty			
Is there a seasonal pattern in positive samples Y□ N□ when reviewing historical monitoring? Other		The sample collector was not properly trained			
Other Y□ N□		Is there a seasonal pattern in positive samples when reviewing historical monitoring?			
	∞	Other			

RTCR Level 1 Assessment Report Form for Positive Total Coliform Investigation

Page 3 of 3